

Arthington Parish Council Annual Parish Inspection 25th June 2019

1. Arthington Lane, (heading eastwards, from Pool to Arthington), Arthington sign obscured by tree leaves/branches.
2. Arthington Lane (heading eastwards), on approach to SID mph sign, the sign is partially obscured by tree leaves/branches making it difficult for drivers to observe their speed.
3. Arthington Lane, adjacent to Arthington Village Hall car park, drain cover in need of attention.
4. Arthington Lane Z bend road sign, for eastbound traffic, located near layby opposite the church, has been knocked and needs straightening.
5. Black Hill Road, bottom and most northern section, gullies on western side of road are blocked and require clearing.
6. Black Hill Road Grass & vegetation by seat at bottom by junction with Arthington Lane, requires strimming – parish council job.
7. Creskeld Lane, Bramhope (below 55 Creskeld Lane), the gullies/pipes which drain water from the road to the stream and culvert below the road are blocked and require clearing. Often a location where the road becomes flooded after heavy rain.
8. Creskeld Lane, Arthington, adjacent to junction with Arthington Lane, width restriction sign on western side of road obscured by tree leaves/branches. Sign also need some realigning.