

Arthington Parish Council Annual Parish Inspection - Compiled 7th July 2020

Due to the Corona Virus Pandemic, this year's Parish Inspection was conducted independently by councillors, and reported back to the Clerk for this document to be complied.

Arthington Garth

- Gutters need clearing
- Potholes on pavements, potential hazard
- Arthington Garth road sign restricted by foliage

West View

- Needs resurfacing at beginning to make entrance level with road and to remove potholes

Station Road/Valley View

- Large potholes near entrance
- Tree trimming near Telegraph pole cables / end house

Creskeld Lane

It was noted that the Lane is generally in good condition.

- Fly tipping halfway up the lane - ACTIONED
- Potholes outside Swiss Cottage – *one pothole has been fixed since being reported*
- Hedge opposite Creskeld Cottages needs trimming - ACTIONED

Bus Shelter

- Roof stone needs reseating/replacing
- Needs weeding out front and leaves sweeping up, general tidy up

Warren Lane:

- Litter in hedges at top half
- Bottom ¼ towards the viaduct is quite muddy and potholed
- Fly tipping in entrance to field next to water works – REPORTED

Arthington Lane / A659:

- 30mph repeater sign between Post Office and School House not visible to traffic coming from west – REPORTED
- Pothole around drain in similar place on north side of carriageway - REPORTED

- Hedge between Post Office and School House needs trimming, encroaching on pavement
- One small pothole outside Village Hall gate – REPORTED
- At “Self-seeded tree bend” the road markings are now non-existent
- Bench at the bottom of Black Hill is in an unsafe state - TO BE FIXED / REPLACED?
- Pavement in need of resurfacing from bend in road to Creskeld Lane
- 40 mph, Arthington Village main 30 MPH road signs all restricted by foliage
- Just after bridge cables across road being interfered with low hanging branches
- Pothole by main drain cover needs repairing
- Hedge trimming along pavement needed

A658 – Foot of Black Hill Road to the Nunnery

- Footpath from bottom of BHR to the church is in very poor condition and the kerb edgings are almost level with the road.

Rawden Hill and Bedlam Lane

- The junction between the two needs attention to potholes and erosion. Bedlam Lane has places where the road edges have been broken away.

Black Hill Road

- Heading north up BHR, the gullies on the right just before the bend need clearing

Approved:

Date: xxx xxx xxx xxx